



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L06-45

Date: 5 SEPTEMBER 2006

Waterway: LAKE SUPERIOR

Location: MICHIGAN

CELRE-OT-T

CONDITION OF FEDERAL NAVIGATION CHANNEL EAGLE HARBOR

1. Surveys performed within the Federal navigation channel at Eagle Harbor, Michigan during July 2006, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L06-45. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Office Home Page.


WILLIAM J. LEADY
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2006.



L A K E S U P E R I O R



Shoals indicate least available depth below LWD

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: July 2006

0eagle.bmp

All soundings are in feet and are referenced to Low Water Datum elevation 601.1 ft. above Mean Sea Level, IGLD, 1985.

EAGLE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 5 September 2006

U.S. Army Engineer District, Detroit